

7B7'9b[]bYYf]b[]'bW
%- '6UW6b'FcUX
9bZjY'X'7H'\$*\$, &

H' fl * \$E'+(- '%+, \$'
: fl * \$E'+*+ '* (*+ '
9]bZc4 V6V6'V6a

Repair Vy Exchange

A cost effective repair option to replace your damaged touch probe

A range of Repair by Exchange (RBE) units are available for several items as a cost effective repair option. The RBE program also has a shorter turn-around time than traditional repair service - the refurbished or as new replacement unit will be shipped to you once the damaged unit is received. RBEs carry a 6 month warranty.

An Advance RBE option is also available for a nominal fee. Customers who choose the Advance RBE option will have their replacement product shipped on the same day that a fault is reported. Advance RBEs also carry a 6 month warranty.

Contact a probe specialist at CNC Engineering for more information and to find out if the Repair by Exchange program is right for you.

